

Bobina d'accensione SKCO-0070174

UMFANGREICHES LIEFERPROGRAMM MIT ÜBER 10.000 VERSCHIEDENEN  
REFERENZE

 Image not found or type unknown

UMFANGREICHES LIEFERPROGRAMM MIT ÜBER 10.000 VERSCHIEDENEN  
REFERENZE

 Image not found or type unknown



## OEM Reference

HITACHI	138757
LAND ROVER	NEC10047
LAND ROVER	NEC10049
RENAULT	7700863020
RENAULT	7700865923
RENAULT	7701041607
ROVER	GCL206
VOLVO	70863020
VOLVO	708630207
VOLVO	70863302

## OEM Cross Reference

BorgWarner (BERU)	0040100245
BOSCH	0986221030
BOSCH	0986221030
METZGER	0880202
MEAT & DORIA	10367
BREMI	11930
INTERMOTOR	12445
INTERMOTOR	12701
INTERMOTOR	12701
HITACHI	138757
HITACHI	138757
HITACHI	138757
HUECO	138757
HUECO	138757
EFI AUTOMOTIVE	155018
VALEO	245066
VALEO	245066
VALEO	245076
VALEO	245076
NGK	48068
HELLA	5DA749475101
HELLA	5DA749475101
HOFFER	8010367
MAPCO	80106
FAE	80220
SIDAT	8530126
SIDAT	8530179
FISPA	8530126
ERA	880018A
FACET	96255
CHAMPION	BAEA245

UMFANGREICHES LIEFERPROGRAMM MIT ÜBER 10.000 VERSCHIEDENEN  
REFERENZE

 Image not found or type unknown

UMFANGREICHES LIEFERPROGRAMM MIT ÜBER 10.000 VERSCHIEDENEN  
REFERENZE

 Image not found or type unknown

**OEM**  
**Cross**